



JON M. HUNTSMAN, JR.
Governor
GARY R. HERBERT
Lieutenant Governor

State of Utah
DEPARTMENT OF NATURAL RESOURCES
Division of Oil, Gas & Mining

MICHAEL R. STYLER
Executive Director

JOHN R. BAZA
Division Director

Supervisor ADZ

Inspection Report
Minerals Regulatory Program
Report Date: June 6, 2005

Mine Name: Lynn Springs Quarry
Operator or Permittee Name:
Bonneville Quarries, Inc.

Permit number: M/003/025
Inspection Date: May 25, 2005

Inspector(s): Lynn Kunzler

Weather: clear
Inspection Start Time: 11:30 am
Inspection End Time: 12:30 pm
Site location/Area Inspected (i.e. Pit #):

Other Participants: None

Permit Status: Active
Current Acreages: 8
Total Permitted (Bonded): 8
Total Disturbed: 8

Surface Ownership: USFS/BLM
Mineral Ownership: BLM
Mineral Mined: Rock
Type of Mine: Surface

Elements of Inspection	Evaluated	N/A	Comment	Enforcement
1. Permits, Revisions, Transfer, Bonds	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
2. Public Safety (open shafts, adits, trash, signs, highwalls)	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
3. Protection of Drainages	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
4. Explosives, magazines	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
5. Deleterious Material	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
6. Roads (maintenance, surfacing, dust control, safety)	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
7. Concurrent Reclamation	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
8. Erosion Control	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
9. Demolition	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
10. Backfilling and Grading (trenches, pits, roads, highwalls, shafts, drill holes)	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
11. Water Impoundments	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
12. Soils	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
13. Revegetation	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
14. Air Quality	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
15. Other	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>

Inspection Date: May 25, 2005; Report Date: June 6, 2005

Page 2 of 2

M/003/025

Purpose of Inspection:

Check status while in the area.


Inspection Summary:

1. This mine operation is active. Mining has stayed within the approved mine area. Quarry Pit is about 10 feet deeper than my last inspection.

6. Access road has been well maintained, and was probably smoother than any other time that I have visited the site. Even with recent heavy rains, drainage and water bars functioned well, with no erosion problems noted.

No other problems noted.

Inspector's Signature _____



Date: June 6, 2005

LK:jb

O:\M003-BoxElder\M0030025-Lynnsprings\inspections\insp-05252005.doc